

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer : KRISHNANUNNI.S
2. Name of the School : Ansar English School, Perumpilavu
3. Location with name of Education District/Sub. District : Perumpilavu/Chavakkad/Kunnamkulam
4. Classification of Building as specified in column 4 of the application for fitness certificate and size

Building No. 744

- GF Class Room 1) 6.30x6.30x3.60 – 5 Nos.
-do- 2) 6.10x5.80x3.60 – 3 Nos.

- Staff Room 3) 4.60 x 6.30x3.60 – 1 No.
-do- 4) 6.50x7.70x3.60 – 1 No.

- Ist floor - Class Room 1) 6.10x6.10x3.45 – 8 Nos.
Staff Room 2) 4.45x6.10x3.45 – 1 No.
-do- 3) 6.50x7.7x3.45 – 1 No.

- IInd floor - Class Room 4) 6.30x6.30x3.45 – 5 Nos.
-do- 5) 6.40x6.00x3.45 – 3 Nos.
-do- 6) 6.50x7.70x3.45 – 1 No.

Building No. 748

- GF Class Room 1) 6.00x6.00x3.80 – 5 Nos.
-do- 2) 6.20x6.00x3.80 – 2 Nos.
-do- 3) 3.90x6.00x3.80 – 1 No.

- Office Room 4) 6.00x6.00x3.80 – 1 No.
Staff Room 5) 4.55x4.60x3.80 – 1 No.

- Ist & IInd floor Class Room 1) 6.00x6.00x3.00 – 10 Nos.
-do- 2) 6.25x6.00x3.00 – 4 Nos.
-do- 3) 3.90x6.00x3.00 – 1 No.
Office Room 4) 6.00x6.00x3.00 – 2 Nos.
Hall 5) 6.00x6.00x3.00 – 1 No.
Staff Room 6) 3.90x6.00x3.00 – 1 No.
-do- 7) 4.55x4.60x3.00 – 2 Nos.

5. Period for which the certificate is issued

2023-24

6. Nature of defects, if any

- a) Foundation and basement
b) Superstructure
c) Doors and Windows
d) Wood work wrought and put up
e) Roof
f) Flooring
g) Miscellaneous (Cracks, etc.)

: NIL

7. Any major defects noticed which will render the building unsafe in any manner

: NIL

8. Whether maintenance works have been done properly : YES

9. Whether the structure is sound or not for conducting classes – Sound and fit under normal wind and weather conditions.

Note: 1 The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by me on 19/10/23 and found to be fit to conduct classes, for the period 2023-24 for the reason stated above.

Place: Karikkad

Date: 20/10/23




KRISHNANUNNI.S
(PEN: 936663)
Assistant Engineer
LSGD (LID & EW) SECTION
KADAVALLUR, KARIKKAD(P.O.)
Thrissur - 680 519